
PRINTORTYPE

CITY OF STOCKTON



Nomination for Designation as a

Historic Site Structure of Merit						
Name of Property: Hotel Main						
Address of Property: 439-447 E. Main St., Stockton, CA						
Property Owner: City of Stockton Economic Development Dept.  Mailing Address: 400 E. Main St., 4th Floor						
Mailing Address: 400 E. Main St., 4th Floor						
Phone: (209) 937-8539 Fax:						
E-mail: - economic. development C stocktonca.gov						
Present use of Property:						
The Name of the Original Owner(s) and/or architect:						
What Year was the Building erected:						
Please provide extensive background information with emphasis on the architectural and/or historical features of the property. Attach photographs, newspaper articles, legal documents or any other material that would assist the Cultural Heritage Board, Planning Commission and City Council in evaluating the nomination. Please refer to Section 16-730.070 of the Stockton Municipal Code to determine the criteria for the designation of Historic Landmarks, Section 16-730.090 for the designation as a Historic Site and Section 16-730.100 for designation as a Structure of Merit.						
The information provided in this application is true and accurate to the best of my knowledge.						
Nominator's Name: Linda Derivi						
Address: 8/15 S. Hwy 26, Valley Springs, CA 95252  Phone: 209-786-2630 or 209-603-2874						
Phone: 209-786-2630 or 209-603-2874						
E-mail: Lmderivi Coutlook.com						
12-20-2018						
Nominator's Signature Date						
Submit Nomination to: Cultural Heritage Board						



c/o Community Development Department 425 North El Dorado Street Stockton, CA 95202-1997

TEL: (209) 937-8444 FAX: (209) 937-8893

CLEAR ALL

PRINT

Exhibit 1

Description (Describe resource and its major elements. Include design, materials, condition, alterations, size,  This is a three-story building located on the northwest corner of E. Main and N. (roof with a detailed parapet and cornice. The fenestration includes single, paire double-hung sash, some of which have arched headers. One set of triple winder floor, have circular pilasters between each windows. Just below each of the thir squares. Separating the first floor from the second floor, is clad with tile. The building portion of the facade on the east side, first floor, is clad with tile. The building portion of the facade on the east side, first floor, is clad with tile. The building portion of the facade on the east side, first floor, is clad with tile. The building on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The building on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The building on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The building on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The building extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The building extending over the side of the properties of t	Date  439-447 E. Main Street  an Joaquin  1/4 of 1/4 of Sec ; B. I  aton Zip 95202  mE/ mN  illon, etc., as appropriate)  Parcel No.  setting, and boundaries)  California Street. The building has a flat ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the solad with floor to ceiling windows. A ling appears to be in good condition.
Other Listings Review Code Reviewer  Get 1 of 3 Resource Name of #: (Assigned by recorder)  Other Identifier: Location: Not for Publication Unrestricted a. County S. and (P2b and P2c or P2d. Attach a Location Map as necessary.)  b. USGS 7.5' Quad Date T; R;  c. Address: 439-447 East Main Street City Stock d. UTM: (Give more than one for large and/linear resources)  e. Other Locational Data (Enter Parcel #, legal description, directions to resource, eleval country of the street story building located on the northwest corner of E. Main and N. (1)  Croof with a detailed parapet and cornice. The fenestration includes single, pairs double-hung sash; some of which have arched headers. One set of triple winder floor, have circular pilasters between each windows. Just below each of the thir squares: Separating the first floor from the second floor, is a simple band of conbuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The build the processor of the sidewalk of the small portion of the facade on the east side, first floor, is clad with tile. The build processor of the processor of the sidewalk of the small portion of the facade on the east side, first floor, is clad with tile. The build processor of the sidewalk of the sidewalk of the first floor of the facade on the east side, first floor, is clad with tile. The build processor of the sidewalk of the first floor of the facade on the east side, first floor, is clad with tile. The build processor of the sidewalk of the sidewalk of the first floor of the facade on the east side, first floor of the facade of the first floor o	### Date  ### 439-447 E. Main Street  ### an Joaquin  1/4 of 1/4 of Sec ; B.I.  ### Brook iton Zip 95202  ### mm  ### mm  ### mm  ### mm  #### mm  #### mm  #### mm  #### mm  #### mm  ##### mm  #### mm  ##### mm  ##### mm  ##### mm  ##### mm  ###### mm  ###### mm  ###### mm  ########
Review Code Reviewer	Date  439-447 E. Main Street  an Joaquin  1/4 of 1/4 of Sec ; B. I ston Zip 95202  mE/ mN  illon, etc., as appropriate)  Parcel No. setting, and boundaries)  California Street. The building has a flat ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the sclad with floor to celling windows. A ling appears to be in good condition.  Didding  Element of District  Other (Isolates, etc.)  Discopping northwest
Description (Describe resource and its major elements, include design, materials, condition, alterations, size,  This is a three-story building jocated on the northwest corner of E. Main and N. Croof with a detailed parapet and cornice. The fenestration includes single, paire double-hung sash, some of which have arched headers. One set of the thin squares. Separating the first floor from the second floor, is alternative band of combuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The building portion of the facade on the east side, first floor, is clad with tile. The building on both sides (List attributes and codes) HP7 -3+ story Commercial B. Resources Present Building Structure Object Site District Of Preserved.	an Joaquin  1/4 of 1/4 of Sec; B.I  Iton Zip 95202  mE/ mN  Illon, etc., as appropriate)  Parcel No.  setting, and boundaries)  California Street. The building has a flat ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the s clad with floor to celling windows. A ling appears to be in good condition.  Lement of District  Other (Isolates, etc.)  Sb. Description of Photo: (View, date, accession #) moto looking northwest
and (P2b and P2c or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T ; R; c. Address: 439-447 East Main Street City Stock d. UTM: (Give more than one for large and/linear resources) e. Other Locational Data (Enter Parcel #, lègal description, directions to resource, eleveration (Describe resource and its major elements. Include design, materials, condition, alterations, size, This is a three-story building located on the northwest corner of E. Main and N. Cornor with a detailed parapet and cornice. The fenestration includes single, paint double-hung sash, some of which have arched headers. One set of triple winds floor, have circular pilasters between each windows. Just below each of the thin squares. Separating the first floor from the second floor is a simple band of combuilding on both sides is an awning extending over the sidewalk. The first floor I small portion of the facade on the east side, first floor, is clad with tile. The build Resources Present ⊠ Building □ Structure □ Object □ Site □ District □ Pegel.	ton Zip 95292  me/ mN  illon, etc., as appropriate)  Parcel No. setting, and boundaries)  California Street. The building has a flat ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the sclad with floor to ceiling windows. A ling appears to be in good condition.  Liding  Element of District  Other (Isolates, etc.)  5b. Description of Photo: (View, date, accession #) moto looking northwest
b. USGS 7.5' Quad Date T; R; c. Address: 439-447 East Main Street City Stock d. UTM: (Give more than one for large and/linear resources) e. Other Locational Data (Enter Parcel #, legal description, directions to resource, eleval Description (Describe resource and its major elements. Include design, materials, condition, alterations, size, This is a three-story building located on the northwest corner of E. Main and N. ( roof with a detailed parapet and cornice. The fenestration includes single, paint double-hung sash, some of which have arched headers. One set of triple winds floor, have circular pilasters between each windows. Just below each of the thin squares. Separating the first floor from the second floor is a simple band of con- building on both sides is an awning extending over the sidewalk. The first floor I small portion of the facade on the east side, first floor, is clad with tile. The build Resources Present ⊠ Building □ Structure □ Object □ Site □ District □ P. P	ton Zip 95292  me/ mm/ illon, etc., as appropriate)  Parcel No. setting, and boundaries)  California Street. The building has a flat ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the sclad with floor to ceiling windows. A ling appears to be in good condition.  Liding  Element of District  Other (Isolates, etc.)  Sb. Description of Photo: (View, date, accession #) moto looking northwest
b. USGS 7.5' Quad  c. Address: 439-447 East Main Street  d. UTM: (Give more than one for large and/linear resources) e. Other Locational Data (Enter Parcel #, legal description, directions to resource, eleval particle.  Description (Describe resource and its major elements, include design, materials, condition, alterations, size, This is a three-story building located on the northwest corner of E. Main and N. Coroof with a detailed parapet and cornice. The fenestration includes single, paint double-hung sash, some of which have arched headers. One set of triple winds floor, have circular pilasters between each windows. Just below each of the thin squares: Separating the first floor from the second floor is a simple band of combuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The build the second second floor is a simple band of constant portion of the facade on the east side, first floor, is clad with tile. The build second se	me/ mN  Iton, etc., as appropriate)  Parcel No.  setting, and boundaries)  California Street. The building has a flat end and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the sclad with floor to celling windows. A ling appears to be in good condition.  Lement of District  Other (Isolates, etc.)  Sb. Description of Photo: (View, date, accession #)  moto looking northwest
c. Address: 439-447 East Main Street City Stock d. UTM: (Give more than one for large and/linear resources) e. Other Locational Data (Enter Parcel #, lègal description, directions to resource, eleveration (Describe resource and its major elements. Include design, materials, condition, alterations, size,  This is a three-story building located on the northwest corner of E. Main and N. Croof with a detailed parapet and cornice. The fehestration includes single, paint double-hung sash, some of which have arched headers. One set of triple winds floor, have circular pilasters between each windows. Just below each of the thin squares: Separating the first floor from the second floor is a simple band of conbuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The build the floor of the facade on the east side, first floor, is clad with tile. The build floor is a simple band of the facade on the east side, first floor, is clad with tile. The build floor is a simple band of the facade on the east side, first floor, is clad with tile. The build floor is a simple band of the facade on the east side, first floor, is clad with tile. The build floor is a simple band of the facade on the east side. The floor is a simple band of the facade on the east side. The floor is a simple band of the floor is a	me/ min
d. UTM: (Give more than one for large and/linear resources)  e. Other Locational Data (Enter Parcel #, legal description, directions to resource, elevaluation (Describe resource and its major elements. Include design, materials, condition, alterations, size,  This is a three-story building located on the northwest corner of E. Main and N. Croof with a detailed parapet and cornice. The fenestration includes single, paint double-hung sash, some of which have arched headers. One set of triple-winder floor, have circular pilasters between each windows. Just below each of the thin squares: Separating the flist floor from the second floor is a simple band of conbuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The build the flight floor of the facade on the east side, first floor, is clad with tile. The build floor from the second floor of the facade on the east side. The floor of the facade on the east side floor of the floor of the facade on the east side. The floor of the floor of the facade on the east side. The floor of the floor of the facade on the east side. The floor of	Parcel No.  Parcel No.  Parcel No.  Setting, and boundaries)  California Street. The building has a flat ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the sclad with floor to celling windows. A ling appears to be in good condition.  Litting  Element of District  Other (Isolates, etc.)  5b. Description of Photo: (View, date, accession #) moto looking northwest
e. Other Locational Data (Enter Parcel #, lègal description, directions to resource, elevalus description). Describe resource and its major elements. Include design, materials, condition, alterations, size, This is a three-story building located on the northwest corner of E. Main and N. Croof with a detailed parapet and cornice. The fenestration includes single, paint double-hung sash, some of which have arched headers. One set of triple winds floor, have circular pilasters between each windows. Just below each of the thin squares: Separating the first floor from the second floor is a simple band of combuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The build the second second floor is a simple band of control of the facade on the east side, first floor, is clad with tile. The build the second	Parcel No.  Parcel No.  Setting, and boundaries)  California Street. The building has a flated and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the sclad with floor to ceiling windows. A ling appears to be in good condition.  Liding  Element of District  Other (Isolates, etc.)  5b. Description of Photo: (View, date, accession #)  moto looking northwest
Description (Describe resource and its major elements, include design, materials, condition, alterations, size,  This is a three-story building located on the northwest corner of E. Main and N. Croof with a detailed parapet and cornice. The fenestration includes single, paint double-hung sash, some of which have arched headers. One set of triple winds floor, have circular pilasters between each windows. Just below each of the thin squares: Separating the first floor from the second floor is a simple band of conbuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The build the floor of the facade on the east side, first floor, is clad with tile. The build the floor of the facade on the east side. HP7 -3+ story Commercial Bis. Resources Present Building Structure Object Site District February Plants of the floor of the fl	Parcel No. setting, and boundaries) California Street. The building has a flat ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the is clad with floor to celling windows. A ling appears to be in good condition.  Didding Element of District  Other (Isolates, etc.) Sb. Description of Photo: (View, date, accession #) moto looking northwest
This is a three-story building located on the northwest corner of E. Main and N. Croof with a detailed parapet and cornice. The fenestration includes single, paint double-hung sash, some of which have arched headers. One set of triple winds floor, have circular pilasters between each windows. Just below each of the thin squares. Separating the first floor from the second floor is a simple band of conbuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The build be resources. Present Building Structure Object Site District February Present Building Structure Object Site District February Present.	Setting, and boundaries) California Street. The building has a flat ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the sclad with floor to celling windows. A ling appears to be in good condition.  California of District  Other (Isolates, etc.)  Sb. Description of Photo: (View, date, accession #) moto looking northwest
This is a three-story building located on the northwest corner of E. Main and N. Croof with a detailed parapet and cornice. The fenestration includes single, paint double-hung sash, some of which have arched headers. One set of triple winds floor, have circular pilasters between each windows. Just below each of the thin squares. Separating the first floor from the second floor is a simple band of conbuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The build be resources. Present Building Structure Object Site District February Present Building Structure Object Site District February Present.	California Street. The building has a flat ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the s clad with floor to ceiling windows. A ling appears to be in good condition.  Didding  Element of District  Other (Isolates, etc.)  Discopping northwest
roof with a detailed parapet and cornice. The fenestration includes single, paint double-hung sash, some of which have arched headers. One set of triple-window floor, have circular pilasters between each windows. Just below each of the third squares. Separating the flist floor from the second floor is a simple band of conbuilding on both sides is an awning extending over the sidewalk. The first floor is small portion of the facade on the east side, first floor, is clad with tile. The build be resource Attributes: (List attributes and codes). HP7-3+ story Commercial Building. Structure. Object. Site. District. First plants.	ed and triple groupings of one-over-one, ows, facing E. Main Street at the third of floor windows is a band of inset crete over plaster. Wrapping around the s clad with floor to ceiling windows. A ling appears to be in good condition.  Litting  L
Resources Present ⊠ Building □ Structure □ Object □ Site □ District □ P	Element of District □ Other (Isolates, etc.)  5b. Description of Photo: (View, date, accession #)  noto looking northwest
Resources Present ⊠ Building □ Structure □ Object □ Site □ District □ P	Element of District □ Other (Isolates, etc.)  5b. Description of Photo: (View, date, accession #)  noto looking northwest
Resources Present ⊠ Building □ Structure □ Object □ Site □ District □ P	Element of District □ Other (Isolates, etc.)  5b. Description of Photo: (View, date, accession #)  noto looking northwest
Resources Present ⊠ Building □ Structure □ Object □ Site □ District □ P	Element of District □ Other (Isolates, etc.)  5b. Description of Photo: (View, date, accession #)  noto looking northwest
Resources Present ⊠ Building □ Structure □ Object □ Site □ District □ P	Element of District □ Other (Isolates, etc.)  5b. Description of Photo: (View, date, accession #)  noto looking northwest
	5b. Description of Photo: (View, date, accession#) noto looking northwest
	noto laoking northwest
	Data Constructed/Arm and Source
	☐ Prehistoric ☑ Historic ☐ Both
	onstructed in 1884.
	7. Owner and Address
	CKeegan, Robert F & A, Tr. Et Al
	56 Wood Duck Circle ockton, CA 98507
PB	. Recorded by: (Name, affiliation, and address)
S P	er 9, The Embarcadero
$S_{\epsilon}$	In Francisco, CA 94111
L pg	Date Recorded: 08/28/2000
	0. Survey Type: (Describe)
Grand Control of the	mited Survey Area
	The transfer of the second of the
Report Citation: (Cite survey report and other sources, or enter "none")	
MERKIT LIBERTING AND AUTOM FORMS AND AUTOM ALANGA PARAMA	

· .						10 18 12
	IA — The Resources Agency OF PARKS AND RECREATION			Primary # .		
BUILDING	3, STRUCTURE, AND OF	SJECT RECOR	D	HRI#	,	
Page 2 of	3		NAHP	Status Code		
	Resource	Name or #: (Assign	ned by records	r) 439-447 E. N	fain Street	
B1. Historic N	lame:					
B2. Common						
B3. Original L		В	4. Present Use:	. Hotel/Comme	rcial .	
	ectural Style: Victorian				1.15	
Bullt in	ction History: (Construction date, 1884. The building has been alte with a cone-shaped roof. In 1975	red over the years.	The comer on	ce had a bay w	vindow on the	upper floors
		• •				
	!?⊠No □Yes □Unknown Date ed Features:	<b>0</b> :	Original Locat	ion: .		·
en. Maidr	w reduies.				t	
• •		.:				
	ct: Unknown		Builder: <i>Unkno</i>	own.		÷.,.
	ficance: Theme: Hotel Architect			: Stockton .	<b>S</b>	Þ
Pertod (Discuss	of Significance: importance in terms of historical or architec	Property Type: Proper	o <i>tel/Commercia</i> theme, period and	A deographic scope	pplicable Cr . Also address inte	iteria: gnty.)
the buili remaine once be 439 - 4 Hotel	d to the Hotel Main by 1925. By ding, and Wilson's News Stand and in the building through 1950. Ben part of the Commercial Hotel, 47 East Main, installed in the 18 prefronts of this building have been	and California Floral The ground floor is next door at 425-29 80s and since remo	Company we currently cons East Main, si East once an	re on N. Califo sumed by K. V. tarting in the 1t nounced the b	mia. All three Furniture. TI 880s. A sign o uilding as the	businesses nis may have on the roof of Commercial
has bee the Nat	en removed, but the upper floors a ional Flegister or Stockton Land fural ments.	are otherwise relativ	ely intact. The	e building does	not meet the	standards of
(See Co	ontinuation Sheet)	.÷			•	
E ann an ast state or						
	al Resource Attributes: (List attribute	s and codes) HP7	- 3+ story Comn	nercial	E1 (1)	
B12. Refer			1 1	1 1		
Culturai	illography for Report Entitled Dow Resources Survey by Architectur	viitown Stockton al Resources	В	ipo _		
Group.						
		•	***	V	VEBER AV	
			100			
B13. Remarks	<b>3</b> :		A L			
1, 5, 1				<u> </u>		
B14. Evalu	ator: Architectural Flesources Granuation: 08/28/2000	oup	Ĕſ	TITTI I	IAIN ST	
Date Of EV			_   Z			11
	(This space reserved for official comm	nents.)			100 m	
				╽╟╏┌╼═┤┤	3	
	·		11		management	
		•			1111	
	,				total photology	.

	and the second before the second of the seco		AND THE PERSON NAMED IN POST OF
Recorded by: Architectural Resources Group	Date 08/28/2000	Continuation	] Update
Page 3 of 3 Resource Name or #: (Assigned by recorder)	439-447 E. Main Street		,
CONTINUATION SHEET	Trinomial		
DEPARTMENT OF PARKS AND RECREATION	H81 #	A Control of the Cont	
State of California — The Resources Agency	Primary #	Control of the State of the State of	

Building, Structure, and Object Record Continued

This resource is a contributor to a potential commercial historic district composed of historic resources along East Weber, East Main, and East Market streets and the north/south cross streets. The Stockton Downtown Commercial historic district is representative of Stockton's commercial development from the 1870s through the 1940s. Along these streets there are a significant number of resources that reflect Stockton's important commercial enterprises and business practices. While it is common for Stockton's downtown commercial structures to be altered at the first story or storefront level, many remain unaltered above the storefront level. As a collection of historic structures this district appears eligible for the National and California Registers, as well as a local district. The district is important as it conveys a strong sense of time and place and represents Stockton's growth as the commercial focus for the surrounding agricultural area, as well as a significant California inland port for the transport of agricultural products. (See District Form)

DPR 523L (1/95) HistoryMaker

San Duenavantura Research Associates

